

## ***FSW NC Force Control Documentation***

### **Contents**


Introduction	1
Force Sensor Setup	2
Analog Input & Conversion	2
Force Calibration	3
Force Control	4
Force Control Scheme	5
NC Program Library Contents	5
NC Main Program Example	6
NC Cycles	7
Global User Data Variables and View	8
PLC Implementations and interface signals	9

### ***Introduction***

Riftec GmbH in Hamburg Germany using a Tricept Robot for friction stir welding applications and have with this project realized a force control implementation, based on Artis DDU4 products and Siemens fast Analog Input options in the control Sinumerik 840D. By installing and connecting this hardware and also provide software solutions with functionality for force control loop, mainly implemented with use of 840D synchronous actions and PLC adaptations. The content of NC functions and the PLC interface functionality will be described in detail below. The cycles are not protected by any way and the source printouts and also the content of this documentation should be handled with care in respect of competition.

## Force Sensor Setup

To read the force and/or the torque from Artis DDU4 tool into the NC, it is using a Sinumerik Analog FastIn DMP module. The DMP module is a fast type of update rate = 75 microseconds. There is no filters activated in the NC for this input, but in the cycles there is an average smoothing done and acts like a filter. At the Artis control side, the filter should be switched off. See setup instructions. Cable is connected to analog force/torque out at the controller to the dmp module. There is some alarm status and reset relay implemented in the plc and wired to the input/output at the controller. See plc doc.




## Analog Input & Conversion

The analog signal is converted to force by a calculation in the FSW\_ANA\_ON.SPF routine. The force range at the sensor holder and the setting at the controller need to be adjusted and also a variable in the cycle routine must be set to the same level. Also the Volt output level +/- 10 V is adapted and can be changed if an output changing. See cycle code and doc below. Also the filter (time) is set by a variable in the cycle R7=100; Update rate in ms. This value will produce a smoothing input value which is averaged.

## Force Calibration


The force relation with machine axis movement is done in a cycle FSW\_FC\_ON.SPF and are updated at lowest interpolator cycle time ( Tricept 6 ms ). Practically this update time is set to 200 ms to adapt to the FSW needs. The FSW tool pin is forced into the material with a tool oriented overlaid movement (\$AA\_OFF[axis]) and the distance per force unit are set by a polynom function with up to a three degree curve, but at this moment only the first degree is used (linear). The gradient of the curve is measured and calculated by running a cycle called FSW\_FC\_CAL.SPF. This cycle will force the tool into the material and measure the machine and material stiffness in relation to the movement to give an approximated start gradient  $a_1$ . This could later be adjusted manually after needs. The input into this function is The difference between actual force (FSW\_ZForceActual) and the force setpoint (FSW\_ZForceSetPoint). This means that the first coefficient  $a_0$  is set to zero. It is also limited by a min and max level variables and listed in the global user data list (MGUD) menu. The polynom curve looks like this:



All coefficients are present in the GUD menu and can be set manually. At a later test stage, there would be a possibility to set more degrees to get a larger reaction near the borders. See Sinumerik Programming Documentation "Polynomial function". The limits are also set by GUD variables, see cycle FSW\_FC\_ON.SPF list below.

## **Force Control**

The correction of the tool is always done in the tool direction (calculated in x,y and z direction) of the machine base coordinate system (BCS). This coordinate system is the same as moving the Tricept in JOG mode following the machine table, i.e Z-tool direction perpendicular to the table surface. The movement is a so called overlaid or superimposed movement which means that there is no tool length compensation to do this, but a strict additive movement to the setpoint of the path. This movement can be seen in the real time variables \$AA\_OFF[X], \$AA\_OFF[Y] and \$AA\_OFF[Z]. The amount depends on the actual tool orientation in the BCS coordinate system. The overlaid compensation is configured to be an "integrated" movement which means that those values is adding at each interpolator time loop limited by the filter(gain) time set in FSW\_FC\_ON.SPF. It is also limited by the actual feedrate override at the machine panel with a linear functionality, so an override set at zero will stop the addition of movement. This total movement is also limited by a GUD variable based on the FSW\_MaxToolLengthComp. This should be set to a value corresponding to an absolute additive movement where it can not destroy the machine by faulty operations and also a practical limit based on acceptable misalignments in frame deviations, i.e. path movement is not following the material to weld. This total overlaid movement can be watched in real-time variable \$AA\_OFF\_VAL. If the limit is hit, the NC calls the retract function and moving away in tool direction with a distance of GUD variable FSW\_ToolRetractDistance. The retract movement could also be called by pushing the "abort/retract" button on the machine panel. The overlaid movement can also be stopped by setting the GUD flag variable FSW\_ZForceOn to off=0 or on=1. This is also a button.



## NC Program Library Contents

Cycles in Work Piece Directory: FSW\_CYCLES

- |                   |   |
|-------------------|---|
| ○ FSW_ANA_ON.SPF  | Switching on analog input with filter time.   |
| ○ FSW_ANA_OFF.SPF | Switching off analog input.   |
| ○ FSW_FC_CAL.MPF  | Measurement and calculation of relation force – tool Distance movement.               |
| ○ FSW_FC_ON.SPF   | Switching on Force regulation.  |
| ○ FSW_FC_OFF.SPF  | Switching off force regulation.   |
| ○ FSW_FC_POS.SPF  | Position into material to a given force.  |
| ○ FSW_EXAMPLE.MPF | Main nc-program example.  |
| ○ GUDUPDATE.MPF   | Nc-cycle running in channel two for updating global user data variables in real time. |
| ○ FSW_REC_ON.SPF  | Switching on log-file recording.  |
| ○ FSW_REC_OFF.SPF | Switching off log-file recording.   |

Cycles in Standard SUBPROGRAM Directory:

- |                   |   |
|-------------------|---|
| ○ FSW_RETRACT.SPF | Asup-cycle for retraction of tool in program or from Machine panel. |
| ○ EASYMASK.SPF    | Asup-cycle for controlling machine panel buttons.                   |



```

FSW_FC_OFF      ; force control off
Z10 F1000       ; retracting to 10 mm above surface
FSW_REC_OFF     ; log data off, saving file
M5              ; stopping spindle
Z100 F5000      ; move to safe height
;home_pos       ; goto home position
M30             ; program end

```

## NC Cycles

Variable explanation of cycles.

FSW\_ANA\_ON.SPF (Switching on analog input with filter time.)

```

FSW_DDU_ForceLimit=10 ; Select 2,5 or 10 kN. This should correspond to the Artis DDU4
                        ; controller setup.
R7=100                ; Update rate in ms. This is the filter time and a possibility to smooth
                        ; the analog input by averaging. Keep filter off at controller and
                        ; smooth here instead.
R8=0                  ; Set VoltInput at zero. It is possible to set zero, i.e if the controller
                        ; could not be adjusted to zero output, put in the offset here.
R9 = 32752/10         ; [Volt input Convert] +/-10 Volt Analog Module. This correspond to
                        ; the Sinumerik Fast Analog Input module hardware which have a
                        ; 11 bit resolution at +/- 10 volt span.
R10 = (FSW_DDU_ForceLimit*1000)/10.0 ; [N per Volt] conversion to Newton per volt input.

;R18                  ;Last calculated analog average value
;R19                  Force Input Value DDU4, averaged value and converted to force [N]. by
                        ; scaling with R9 and R10. (Artis outputs a minus value in tool direction, therefore a
                        ; minus sign in R19 calculation.
;R20                  Force value in, ActualForce - ForceSetPoint
;R21                  Force value in, ActualForce - ForceSetPoint * ForceOverride

```

FSW\_FC\_CAL.MPF (Measurement and calculation of relation force – tool distance movement.)

```

FSW_ZForceSetPoint=3000 ;Set force level [N] to reach at force test. This
                        ; should be equal or over an estimated force setpoint
                        ; in the application tested for.
ForceLevelStart=200     ;Start point in force, i.e a smaller force at measuring
                        ; start to avoid misreading values.
ForceSetPointDeltaMeas=500 ;Force span [N] of measurement. This span
                        ; effecting the calculated slope average.
ToolDistanceMax=0.5     ;Limit for max correction value [mm]
ToolDistanceStep=0.001  ;Loop step distance when moving into material [mm]
StepFeedrate=500        ;Feedrate of infeed movement [mm/min]

```

R23=200 ;update rate time of force cycle [ms]. This value correspond to a "gain" factor in combination with polynomial coefficient FSW\_DDU\_PolynomCoffA1

\$SA\_AA\_OFF\_LIMIT[Axis] ; Limit the overlaid integrating movement as GUD FSW\_MaxToolLengthComp)

FSW\_ZForceOn=1 ; Forcing the GUD variable to 1 at start.  
 FSW\_ToolRetractOn = 0 ;switch off Retract Flag.  
 ; \$A\_DBB[2] ;Force Override factor , set by plc  
 ; R21 ; ForceInput = ForceActual  
 ForceSetpoint\*ForceOverride

FSW\_DDU\_PolynomCoffA0=0 ; using setpointdiff R21 instead off offset, crossing at zero

If limit \$AA\_OFF\_LIMIT[X] is reached, nc calls Retract subprogram.

**FSW\_FC\_POS.SPF (Position into material to a given force. )**

ForceLevelStart=50 ;Smaller force at rest position[N]  
 ForceSetPointStart=2500 ;[N] ;When this force is reached, leave the subprogram and switch on force control.

ToolPointLength=0.9 ;[mm] ; The small tap length at the edge of the FSW pin to the shoulder.

ToolDistanceMax ; total length of tool including.  
 ToolDistanceStep=0.01 ;[mm] ; Step  
 StepFeedrate=300 ;Plunging Feedrate [mm/min]

**Global User Data Variables and View**

Global data def for friction steer welding application.

FSW\_Feedrate ;Actual Setpoint Feedrate [mm/min]  
 FSW\_RotDir ;Spindle rotation CW=3/CCW=4  
 FSW\_Speed ;Spindle speed[rpm]  
 FSW\_SpeedChange ;Programmed Acceleration with NC command ACC[axis] [rpm/sec] (option)

FSW\_MaxToolLengthComp ;Used to calculate max limits [mm]  
 FSW\_ZForceOn ;Force Control Flag , OFF=0/ON=1  
 FSW\_ZForceActual ;Actual Force input from analog in converted [N]  
 FSW\_ZForceSetPoint ;Setpoint for force control [N]  
 FSW\_ZForceMax ;Max force for control [N]

FSW_ForceOverride	;Displaying the machine panel override status [%]
FSW_ZForceMaxChangeRate	;Plus Limit for step force/overlay polynom [N/sec]
FSW_ZForceMinChangeRate	;Minus Limit for step force/overlay polynom [N/sec]
FSW_RecordStatus	;Possibility to switch on logfile , OFF=0/ON=1
FSW_RecordSeqNumber	;Internal counter counting up at every call to RecOn.
FSW_RecordFileName	;Path string for logfile name.
FSW_DDU_ForceLimit	;Setable Force Limit [kN]
FSW_DDU_ZeroForceAnaOut	;Zero point for Analog Input[V]
FSW_DDU_MaxForceAnaOut	;Max limit for Analog Input[V]
FSW_DDU_MinForceAnaOut	;Min limit for Analog Input[V]
FSW_DDU_PolynomCoffA0	;Defined offset in polynom
FSW_DDU_PolynomCoffA1	;Defined first degree (linear) in polynom
FSW_DDU_PolynomCoffA2	;Defined second degree in polynom
FSW_DDU_PolynomCoffA3	;Defined third degree in polynom
FSW_SetForceCal	;Setpoint force calibrated
FSW_WeightFactor	;ForceLimit calc
FSW_ToolRetractOn	;OFF=0/ON=1
FSW_ToolRetractDistance	;[mm]
FSW_ToolRetractFeedrate	;[mm/min]

## ***PLC Implementations and interface signals***

Some functions is set by the plc, so therefore this is a list of existing common nc interface variables are listed here:

\$A_DBB[1]	;
\$A_DBB[2]	; Force Override Value at panel. Factor 0-120%
\$A_DBD[8]	; Used by EasyMask.spf (asup) selecting button row
\$A_DBD[12]	; Machine panel Push button code in EasyMask.spf (asup)
\$A_DBD[24]	; flag for FSW_ZForceOn
\$A_DBD[16]	;flag for calling asup retract in channel 1
\$A_DBD[16]	;flag for retracting tool routine.
\$A_DBD[20]	;actual min force variable
\$A_DBD[28]	;actual force value in synchronous action.
\$A_DBD[32]	; Force Override Factor
\$A_DBD[36]	; Force SetPoint
\$A_DBW[4]	;Used by EasyMask.spf (asup) selecting screen button